

09,761,468

10 —

Manufacture to Original Size and
Shape, and Cross-Link

20 —

Stretch to Second Size and
Shape while Energy is Applied;
Effective or Actual Temperature \geq
Transition Temperature

30 —

Reduce Effective or Actual Temperature
while Still Stretched to Second
Size and Shape

Use

Figure : 1